INSTRUCTIONS FOR USE

GOLDEN MASK METAL DETECTORS

MODELS: 1/1+/1+ UK EDITION



INSTRUCTIONS MANUAL

CONTENTS

THE DEVICE	3
METAL DETECTOR OPERATORS ETHICS	3
FITTING GOLDEN MASK 1	
TECHNICAL CHARACTERISTICS	4
STRUCTURE AND OPERATION	5
MAINTAINANCE	7
WARRANTY	

THE DEVICE

The detector consists of: a coil, a strip /connecting the coil to the electrical set/, electrical set, armrest and a battery box.

Searching coil /Coil/

The coil of Golden Mask 1+ is 9 inch DD sized. It's made of plastic as in its lower side it is poured on resin which makes the whole construction very heavy and airproof. The coil is highly sensitive towards as small and big objects.

Additional coils

Golden Mask 1+ can work with additional coils DD: 5", 7", 8",9", 10.5", 12", 12.5",9x10",10x12",", 12.5x15"

Smaller sized coils possess better sensitivity to smaller objects /such as coins/ and are preferably used in heavy mineralized and dirty soils /especially concentric soils/ Bigger coils /12, 12,5x15) are much sensitive to bigger objects and are suitable to be used for searching deeper buried objects, and possess 10-20% better sensitivity than DD 10,5 inch

Strip

The strip is made of aluminum tube, as in its lower side it's made of carbon in order to not disturb the work of the coil.

Electrical set box

It is made of plastic of the well known company BASF and is extremely strong!

Armrest

It is made of aluminum profiles for better strength. In its front side is placed the foam coated handle.

Battery box

It is made of plastic with a slot for 10 batteries NiMH- 1,2V/900mA.

METAL DETECTOR OPERATORS ETHICS

- Please, pay respect to the personality and property of the others;
- Always ask for permission for searching in private property;
- Do not make dirty environment while searching;
- Fill with soil back dug plots;
- Follow all laws and other normative for searching objects in the country you are searching;

- Do not dig historical or archeological objects;
- Before start looking for different objects, read carefully normative legislation of the country, regarding rights of property over found objects and those, which concern cultural belongings of the country.

FITTING GOLDEN MASK 1+

Take the lower end of the strip and put it in the slit of the coil till them both fit tight. Put the plastic bolt into the opening and fit it tight so that it goes out the opposite side and turn the nut with light clamp. Then fit together with the second part of the strip and put the iron bolt while tighten it by the winged nut. Take the electronic set and unscrew the plastic nut and then slide it into the upper end of the tube of the strip, press hard the plastic end of the detector towards the tube of the strip. Put the two tubes one into another as high according to your height. After that tighten the nut heavily so that detector can't move toward the strip. Wind up the cable around the strip leaving an "ear" of the cable on the lower end of the coil so that

the cable wouldn't tear when the coil is gathered and ready to be transported. Then put the jack of the cable into the nest of the detector winding it tightly without much strength. So the detector is ready to be worked with.

TECHNICAL CHARACTERISTICS

- High power electronics
- Work frequencies:
- Golden Mask 1-8KHz
- Golden Mask 1+- 18 KHz
- Golden Mask 1+ UK- 15 KHz
- VLF-TR technology
- Discrimination by moving the coil
- Audio discrimination:
- Golden Mask 1,1+ single ton
- Gold Mask 1+UK Two tones
- Eliminates soils and heavy mineralization
- Automatic ground balance
- Light indicator for the condition of batteries
- Minimal consumption 35 mA
- Maximum consumption 65 mA

- Rechargeable batteries 12V/ 1000 mA
- Automatic charge device with
 years warranty of electronics

STRUCRURE OPERATION

AND



- Pot "THRESHOLD" - used for adjusting sound level and regulates depth. To reach maximum depth, turn the pot on the right till reaches its sound level.

:

- Pot "DISC LEVEL" regulates degree of elimination of iron metals;
- Jack ,,HEADPHONES" –used for headphones;

- Light indicator



LOWBATTERY" – indicates lower tension of batteries.




- Volume control /Golden Mask 1+/ Turning the potentiometer on the left, till it stops - there will be no sound. Turning it on the right, GM 1+ will increase the sound.



- Volume – On/Off

The Uk Edition has an On/Off switching potentiometer. When switched into On, turning it right you will increase the sound.

Searching metal objects is made by moving search coil toward ground surface /fig.1; fig.2/.




*Adjusting the settings

The intensity of separating metals is done with the help of the pot "DISC LEVEL". If you come upon non-ferrous metals /gold, silver, copper, bronze/ a deep-toned sound can be heard; and if you come upon ferrous metals a break or a short sound is heard. Recommended settings are marked with red.

If you wish to eliminate much more non-ferrous metals of earth surface, the pot must be set in a position 8 to 10.

Precise position of a metal can be fixed with the help of movements of searching coil into two perpendicular axes.



* Recharging the batteries.

Batteries possess about 500-600 cycles of re-charge before they

damage, but these are values that can be reached in certain laboratory conditions. The detector is supplied with NiMh batteries. Before start working with the detector batteries have to be charged with the help of the charge device which is also included in the set. Once charged, batteries can be used about 40 hours.

If a light "Low battery" appears while using the detector that means you have to stop using it and recharge the batteries. Put the jack of the charge device into "CHARGE" nest and place the device into electric net from 100 to 250V. All Golden Mask metal detectors come with a smart charger. The smart automatically recognise charger when the battery is full. When this happens the red light will change to green. It's not necessary to keep eyes on charge device, because it is supplied with automatic turn off and batteries couldn't be damaged no matter how long they will stay in the charge device. When they are ready pull the device out of the electric net and take the jack out of the "CHARGE" nest.

MAINTAINANCE

Keep your detector of blows, jars and plunges in water the electronics. Coils are waterproof and they can be plunged. Do not open battery box. If it's necessary, please inform the seller or the service-man. If you stop using the detector, blow dust and send away of the apparatus and wipe it with a wet piece of cloth. Do not use alcohol, spirits, benzine or other diluents. If you use the detector in parcels where ammunitions or other explosives can be localized be careful - the producer or the seller are not responsible for your actions.

Warranty

The detector Golden Mask 1/1+/1+ UK Edition is offered with 5 years of guarantee of electronics, labour and materials used, for harms which are not caused on purpose or irresponsibly. We can upkeep your device after period of guarantee if it is necessary.

Attention: Do not turn on the detector if there are big temperature amplitudes outdoor and indoor in a hot room. Wait for 20-30 minutes and start using the detector.

Do not turn on the device while batteries are re-charging. This can damage electronics.

GOOD LUCK!

Warranty and Service

Warranty card №	/ Date:	
User:		
ATI Group Ltd Luka Kasarov 26 Str. 4000 Plovdiv Bulgaria		
Tel. +359 (0) 896 813 215; +359 (0) 877 Email: thracemd@gmail.com	389 500	

The **Golden Mask 1** metal detector has a **5 years** warranty of the electronics covering the labor costs and materials, and damages not resulting from deliberate or negligent actions.

The warranty is voided in the cases of mechanical damage to the respective components, incorrect use or unauthorized access and repair (opening of the electronic block or the power block, wearing, breaking or damaging the search coil, the cable and cable plug, damaging the battery as a result of using other chargers, using incompatible search coils). To undergo repair under warranty, the metal detector must be shipped to our service office.

All shipment and delivery fees are paid by the customer.

Description of warranty problems:

www.thrace-detectors.com

No	Date	Description of a problem	Solution